

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2016

Document Number:

680400829

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 229047 | 314560 | BROWNING, CHUCK | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON RD

City: RANGELY State: CO Zip: 81648

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|-----------------------|
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com | Regulatory Specialist |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Compliance Summary:

QtrQtr: NWSW Sec: 18 Twp: 2N Range: 102W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 06/04/2015 | 668403059 | IJ | AC | SATISFACTORY | | | No |
| 05/19/2014 | 668402067 | IJ | AC | SATISFACTORY | P | | No |
| 04/11/2013 | 668401067 | IJ | AC | SATISFACTORY | P | | No |
| 05/23/2012 | 668400455 | IJ | AC | SATISFACTORY | | | No |
| 05/17/2011 | 200311193 | RT | AC | SATISFACTORY | | | No |
| 05/17/2010 | 200254510 | RT | AC | SATISFACTORY | | | No |
| 06/09/2009 | 200213813 | RT | AC | SATISFACTORY | | | No |
| 05/16/2008 | 200192267 | MI | AC | SATISFACTORY | | | No |
| 05/10/2007 | 200112319 | RT | AC | SATISFACTORY | | Pass | No |
| 05/16/2006 | 200092026 | RT | AC | SATISFACTORY | | Pass | No |
| 05/12/2005 | 200072689 | RT | AC | SATISFACTORY | | Pass | No |
| 05/10/2004 | 200056155 | RT | SI | SATISFACTORY | | Pass | No |
| 05/20/2003 | 200043420 | RT | SI | SATISFACTORY | | Pass | No |
| 05/15/2002 | 200026628 | RT | SI | SATISFACTORY | | Pass | No |
| 05/17/2001 | 200018610 | MI | SI | SATISFACTORY | | Pass | No |
| 05/30/2000 | 200008998 | RT | SI | SATISFACTORY | | Pass | No |

Inspector Comment:

Routine UIC inspection.

Related Facilities:

Inspector Name: BROWNING, CHUCK

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 229047 | WELL | IJ | 01/01/1999 | ERIW | 103-06125 | GRAY B-9 | AC | <input checked="" type="checkbox"/> |
| 269565 | PIT | AC | 09/26/2003 | | - | GRAY B 21X | AC | <input type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|---------|-------------------|------|
| Main | SATISFACTORY | | | |
| Access | SATISFACTORY | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
| | | | | |

☐ Multiple Spills and Releases?**Fencing/:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Equipment:

| Type: | # | Satisfactory/Action Required: | |
|-------------------|---|-------------------------------|-------|
| Comment | | | |
| Corrective Action | | | Date: |

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | | |
|--------------------|------------------------------|--|
| Type | Satisfactory/Action Required | |
| Comment: | | |
| Corrective Action: | Correct Action Date: | |

Predrill

Location ID: 229047

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 229047 | Type: WELL | API Number: 103-06125 | Status: IJ | Insp. Status: AC |
|---------------------|------------|-----------------------|------------|------------------|

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC RoutineInj./Tube: Pressure or inches of Hg 1356
(e.g. 30 psig or -30" Hg)Previous Test Pressure _____ MPP _____
Inj Zone: WEBR

TC: Pressure or inches of Hg 0

Previous Test Pressure _____ Last MIT: 04/11/2013

Brhd: Pressure or inches of Hg 0

Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC inspection. Active injection at time of inspection. Casing blowdown 0 sec.

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Gravel | Pass | SI | Pass | |

Inspector Name: BROWNING, CHUCK

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 680400829 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3893525 |