



Photo 1. View of the well head facing northward. Project area is located in a camp within a manicured grassy area. Vegetation in project area is approximately the same as surrounding campground and cabin area.





Photo 2. View of well head facing southward.



Photo 3. View of the well head facing eastward.





Photo 4. View of the wellhead facing westward.





Photo 5. Birdseye view of the well head with a stake inside of pvc pipe.