

Margaret Spaulding 2

Inspection# 673403372

Chemical tote at wellhead without secondary containment. Stained soil and below surface sump pump. Absorbent pads around wellhead.

