

Construction Inspection

07/06/2016

Operator: Whiting

Location ID: 444465

Weld County, CO

SWSE Section 25 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from the northeast end of the location, facing west. Photo shows stormwater control ditch around perimeter of the location.



Figure 2: Photo taken from the northeast end of the location, facing south. Photo shows stormwater control ditch around perimeter of the location.



Figure 3: Photo taken from the northeast end of the location, facing south. Photo shows topsoil berm(s) on the east end of the location.



Figure 4: Photo taken from the southeast end of the location, facing north. Photo shows stormwater control ditch around perimeter of the location.



Figure 5: Photo taken from the southeast end of the location, facing west. Photo shows stormwater control ditch around perimeter of the location.



Figure 6: Photo taken from the southwest end of the location, facing east. Photo shows stormwater control ditch around perimeter of the location.



07.05.2016 12:26

Figure 7: Photo taken from the southwest end of the location, facing north. Photo shows stormwater control ditch around perimeter of the location.



Figure 8: Photo taken from the northwest end of the location, facing south. Photo shows stormwater control ditch around perimeter of the location.



Figure 9: Photo taken from the northwest end of the location, facing east. Photo shows stormwater control ditch around perimeter of the location.