



Photo#1: 6/13/16 Overview of Location construction from Access Road Entry.

June 23, 2016

Inspection Photos: RedWine DA 081-07355



Photo#2: : 6/13/16 Overview of Location construction from top of Cut Slope.

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#3: 6/13/16; SW Ditch installed around Perimeter of Location.

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#4: SW Ditch at East side of Location.

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#5: Conductor being removed from Location.

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo #6: Cutting off Rat Hole/Mouse Hole

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#7: 6/14/16; View of Location Construction

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#8: One site at top, of Cut Slope determined to be Top Soil Stockpile

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#9: Overview of Location 6/20/16.

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#10: View Up Slope to West of Completed Dirt/Contouring Work.

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#11: View to North of Completed Dirt/Contouring Work.

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#12:: Slash Pile to be incorporated into SW Plan/BMPs

Inspection Photos: RedWine DA 081-07355

June 23, 2016



Photo#13: Access Road to be Cross Ripped Stabilizing Location until Seeding Activities in Fall 2016.

Inspection Photos: RedWine DA 081-07355

June 23, 2016