



photo 1: Northwest corner of the location facing east. County road Q is shown in the upper left of the photo.



photo 2: Northwest corner of the location facing southeast



photo 3: North side of the location facing south.



photo 4: Northeast corner of the location facing southwest. There are patches of crop growth which indicate the location had been planted with a crop.



photo 5: East side of the location facing northwest. There is no crop growth in this area.



photo 6: Southeast corner facing northwest.



photo 7: Southwest corner of the location facing northeast.



photo 8: West side of the location facing south. There is no crop growth in this area.



photo 9: There is undesirable and noxious weeds (field bindweed) noticed throughout the location.



photo 10: There is undesirable weed growth (kochia, russian thistle) throughout the location.



photo 11: Facing south toward the surrounding crop adjacent to the location. The crop has recently been harvested.