

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
07/06/2016  
Document Number:  
685300869  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>215420</u>	<u>325816</u>	<u>St John, William (Cal)</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>10000</u>
Name of Operator:	<u>BP AMERICA PRODUCTION COMPANY</u>
Address:	<u>380 AIRPORT RD</u>
City:	<u>DURANGO</u> State: <u>CO</u> Zip: <u>81303</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

**Compliance Summary:**

QtrQtr: NWNW Sec: 19 Twp: 33N Range: 6W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/20/2012	669400058	PR	PR	SATISFACTORY	I		No
04/11/2007	200120390	PR	PR	SATISFACTORY			No
12/19/2005	200085728	PR	PR	SATISFACTORY		Pass	No
08/06/2004	200062847	PR	PR	SATISFACTORY		Pass	No
11/21/2002	200032883	PR	PR	SATISFACTORY		Pass	No
04/18/2001	200016522	BH	PR	SATISFACTORY		Pass	No
04/11/2000	200006800	BH	SI	SATISFACTORY		Pass	No
01/10/2000	200003959	PR	PR	SATISFACTORY		Pass	No
04/23/1997	500149069	BH	PR			Pass	No
04/04/1996	500149068	BH	PR			Pass	No
12/05/1995	500149067	PR	PR			Pass	No
08/10/1993	500149066		PR				

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115837	PIT		09/23/1999		-	STATE GU "B2" 1	<input type="checkbox"/>
215420	WELL	PR	12/31/2001	GW	067-07025	STATE COM BZ 1	PR <input checked="" type="checkbox"/>

<b>Equipment:</b>		<u>Location Inventory</u>	
Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Lease Road:</b>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY	Post and Wire		

<b>Equipment:</b>				
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	Telemetry Equipment			
Corrective Action		Date:		
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action		Date:		
Type: Flow Line	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				

Corrective Action		Date:
Type: Vertical Heated Separator	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:
Type: Ancillary equipment	# 1	Satisfactory/Action Required: SATISFACTORY
Comment Wellhead		
Corrective Action		Date:
Type: Deadman # & Marked	# 4	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:
Type: Bird Protectors	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:

**Facilities:**       New Tank      Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL	,
S/AR	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	95 BBLs
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

**Venting:**

Yes/No	NO
Comment	

**Flaring:**

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

**Predrill**

Location ID: 215420

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 215420 Type: WELL API Number: 067-07025 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

<b>Water Well:</b>		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
<b>Field Parameters:</b>			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____ Wildlife Protection Devices (fired vessels): _____			

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Compaction	Pass	MHSP	Pass	

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_  
Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT