



**photo 1:** Aerial image of the location. The red arrow points to areas where erosion was noticed. The yellow arrow points to where Canada and Bull thistle was found.



**photo 2:** Area of erosion along the access road south of the location.



**photo 3:** Facing northwest toward the location.



**photo 4:** Facing toward the east side of the location.



**photo 5:** There is a patch of Canada thistle growing along the east side of the location.



**photo 6:** Bull thistle was also found at the east side of the location.



photo 7: Facing east toward the location.



photo 8: There is erosion occurring along the access road west of the location.