



photo 1: Facing southeast along the reclaimed access road toward the location.



photo 2: The vegetation is not established along the slope (former access road).



photo 3: View of the vegetation cover along the slope. There is field bindweed growing along this area.



photo 4: Facing back to the northwest along the slope.



photo 5: Facing east toward the location.



photo 6: There is noxious weeds (Canada thistle) growing at the north and east side of the location.



photo 7: The Canada thistle is beginning to develop seed head.



photo 8: East side of the location facing west.