

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2016

Document Number:

685500047

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	202480	320066	MONTOYA, JOHN	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Condill, J.B.		jbcrog@aol.com	
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections

Compliance Summary:QtrQtr: NWSE Sec: 33 Twp: 2S Range: 64W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/05/2014	671101897	PR	PR	ACTION REQUIRED	P		No
12/03/2008	200207622	PR	PR	ACTION REQUIRED			Yes
01/04/2001	896539	PR	PR	ACTION REQUIRED		Fail	Yes
01/02/1997	500132491	PR	PR			Fail	Yes

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113191	PIT		08/25/1999		-	CHAMPLIN 248 AMOCO C2	<input type="checkbox"/>
202480	WELL	PR	11/24/1982	OW	001-07885	CHAMPLIN 248 AMOCO C 2	PR <input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location				
<u>Lease Road:</u>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			
<u>Signs/Marker:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	se cornern39.49883w- 104.33166		
Emergency Contact Number (S/AR): <u>SATISFACTORY</u> Corrective Date: _____				
Comment: _____				
Corrective Action: _____				
<u>Good Housekeeping:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TRASH	ACTION REQUIRED	trash inside pum jack samaon posts	"Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P."	09/08/2016
<u>Spills:</u>				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 1 bbl	"Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff."	09/08/2016
Crude Oil	Truck Loadout	<= 1 bbl	"Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O."	09/08/2016
Lube Oil	Pump Jack	<= 1 bbl	"Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff."	09/08/2016
<input type="checkbox"/> Multiple Spills and Releases?				
<u>Fencing/:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
<u>Equipment:</u>				
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required:	ACTION REQUIRED	
Comment	no bird protection			
Corrective Action	"Install wildlife screen per Rule 605.b.(7)."			Date: 9/8/2016
Type: Pump Jack	# 1	Satisfactory/Action Required:	ACTION REQUIRED	
Comment	gear box leaking, needs repaired			
Corrective Action	"Remove free fluids and contact COGCC EPS staff per Rule 906.b."			Date: 9/8/2016
<u>Venting:</u>				
Yes/No				
Comment				

Flaring:

Type	Satisfactory/Action Required	
Comment:		
Corrective Action:		Correct Action Date:

Predrill

Location ID: 202480

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 202480 Type: WELL API Number: 001-07885 Status: PR Insp. Status: PR

Producing WellComment: **PR****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: MONTOYA, JOHN

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: MONTOYA, JOHN

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
DOCUMENT # 671101877 dated 9/5/14 soiled dirt at wellhead, soiled dirt around motor mount and lube oil inside pump jack area, soiled dirt load line and leaking 3inch line and leaking vic clamps, all these problems still exist	montoyaj	07/08/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685500047	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898320
685500049	well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898299
685500050	well head soiled dirt	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898300

685500051	gear lube on ground	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898301
685500052	soiled dirt motor mounts	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898302
685500053	exhaust soiled dirt	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898303
685500054	soiled dirt gear lube	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898304
685500055	trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898305
685500056	tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898306
685500057	load lin soiled dirt no cap on load line valve	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898307
685500058	2inch drain staine soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898308
685500059	soiled dirt vic clamp leaking	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898309
685500060	3 inch valve leaking replace or repair	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898310
685500061	no bird protection	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898311