

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
07/07/2016
Document Number:
674901199
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>214577</u>	<u>312071</u>	<u>Hughes, Jim</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10000</u>
Name of Operator:	<u>BP AMERICA PRODUCTION COMPANY</u>
Address:	<u>380 AIRPORT RD</u>
City:	<u>DURANGO</u> State: <u>CO</u> Zip: <u>81303</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Compliance Summary:

QtrQtr: NESE Sec: 3 Twp: 33N Range: 8W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/04/2015	667100366	PR	PR	SATISFACTORY	I		No
07/21/2014	669500207	PR	PR	ACTION REQUIRED	I		No
08/23/2012	669400072	PR	PR	SATISFACTORY	I		No
03/09/2009	200205105	ID	SI	SATISFACTORY			Yes
06/18/2007	200120533	PR	PR	SATISFACTORY			No
01/13/2006	200087748	PR	PR	SATISFACTORY		Pass	No
01/22/2004	200052436	PR	PR	SATISFACTORY		Pass	No
03/04/2003	200037938	PR	PR	SATISFACTORY		Pass	No
07/10/2001	200019390	PR	PR	SATISFACTORY		Pass	No
02/08/2000	200004328	PR	PR	SATISFACTORY		Pass	No
02/03/1998	500147563	PR	PR			Pass	No
01/22/1998	500147562	PR	PR			Pass	No
03/18/1996	500147561	PR	PR				No
07/28/1994	500147560	PR	PR			Pass	No
05/27/1994	500147559		PR				

Inspector Comment:

On July 7, 2016 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Ford D #1. For the most recent field inspection report of this facility, please refer to document #667100366.

Related Facilities:

Inspector Name: Hughes, Jim

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
214577	WELL	PR	12/01/2014	GW	067-06181	FORD D 1	EI	<input checked="" type="checkbox"/>
216300	WELL	PR	03/14/2006	GW	067-07906	DODD 3-2	PR	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY	Free standing sign near PBV.		
WELLHEAD	SATISFACTORY	Free standing sign near well head. One of the supports for the sign is broken.		

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY	Stock panel fencing surrounds PBV.		
WELLHEAD	SATISFACTORY	Well head protected by jersey barriers and steel pipe barricade.		
SEPARATOR	SATISFACTORY	All equipment on location has stock panel fencing.		

Equipment:			
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment	Telemetry		
Corrective Action		Date:	
Type: Gas Meter Run	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	
Type: Bird Protectors	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL	37.129441, -107.699234
S/AR	SATISFACTORY		Comment:	
Corrective Action:		Corrective Date:		

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) 95 bbl. _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 214577

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 214577 Type: WELL API Number: 067-06181 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: Hughes, Jim

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On July 7, 2016 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Ford D #1. For the most recent field inspection report of this facility, please refer to document #667100366.	hughesj	07/08/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901199	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898358
674901200	Rip rap run down.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898356
674901201	Rip rap and wattles.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3898357