

Final Reclamation Inspection



Photo 1. Photo taken from south of location, facing North. Equipment and debris (i.e. railroad ties) needs to be removed per Rule 1004.

Final Reclamation Inspection



Photo 2. Close up photo taken of equipment and debris (i.e. railroad ties) needs to be removed per Rule 1004.