



Produced water pit: Looking south from north end of pit. Free oil is present on surface. Evidence of skim pit overflow is present on southwest corner of pit.



Dead birds beneath netting on south pit wall.



Gap in netting on south end of pit.



Dead birds around outflow from skim pit.



Sag in netting from broken cable is center of picture.



Unlined skim pit (tin horn) located on southwest corner of produced water pit.