

Inspector Name: Sherman, Susan

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2016

Document Number:

673713519

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	233364	316942	Sherman, Susan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 14855Name of Operator: CENTRAL OPERATING INCAddress: 1600 BROADWAY STE 1050City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Vasina, Heather	(303) 894-9576	centraloperating@aol.com	
Crumley, Luke	(970) 324-0060	crumleypumping@gmail.com	
Quint, Craig		craig.quint@state.co.us	

Compliance Summary:QtrQtr: SENW Sec: 25 Twp: 3S Range: 51W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/05/2015	673710344	SI	SI	SATISFACTORY			No
05/27/2014	673703619	SI	SI	SATISFACTORY			No
06/28/2013	664001096	SI	SI	SATISFACTORY			No
07/13/2012	663400606	SI	SI	ACTION REQUIRED	P		No
04/29/2011	200309000	RT	AC	SATISFACTORY			No
06/28/2010	200258602	RT	AC	SATISFACTORY			No
08/03/2009	200216057	MI	TA	SATISFACTORY			No
07/06/2009	200214078	RT	AC	SATISFACTORY			No
04/16/2008	200130365	RT	AC	SATISFACTORY			No
10/10/2007	200120860	MI	PD	SATISFACTORY			No
05/04/2007	200111086	ID	SI	ACTION REQUIRED		Fail	Yes
10/27/2005	200079295	ID	SI	ACTION REQUIRED		Fail	Yes
09/05/2002	200030092	PR	PR	SATISFACTORY		Pass	No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159191	UIC DISPOSAL	AC	12/19/2007		-	JONES #1 - SWD	AC

Inspector Name: Sherman, Susan

233364	WELL	SI	04/29/2009	DSPW	121-05400	JONES 1	SI	<input checked="" type="checkbox"/>
--------	------	----	------------	------	-----------	---------	----	-------------------------------------

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type: Ancillary equipment	# 3	Satisfactory/Action Required: SATISFACTORY
Comment	2 Y-W Poles, shed	
Corrective Action	Date:	
Type: Deadman # & Marked	# 4	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date:	

Facilities:☐ New Tank

Tank ID: _____

Inspector Name: Sherman, Susan

Contents		#	Capacity	Type	SE GPS		
				CENTRALIZED BATTERY	,		
S/AR			Comment:				
Corrective Action:						Corrective Date:	
Paint							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Corrective Action						Corrective Date	
Comment							
Venting:							
Yes/No							
Comment							
Flaring:							
Type		Satisfactory/Action Required					
Comment:							
Corrective Action:						Correct Action Date:	

Predrill

Location ID: 233364

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** SATISFACTORY**Comment:** No COAs.**CA:** _____**Date:** _____**Wildlife BMPs:****S/AR:** _____**Comment:** _____**CA:** _____**Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 233364

Type: WELL

API Number: 121-05400

Status: SI

Insp. Status: SI

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg 0 _____ Previous Test Pressure _____ Last MIT: 05/27/2014

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: **SI. Slight blow down on tubing that died immediately. May 2016 reported to COGCC production database. Couldn't get Bradenhead open.**

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: **open range**

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Inspector Name: Sherman, Susan

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Inspector Name: Sherman, Susan

Compaction	Pass	Compaction	Pass			
S/A/V: SATISFACTOR Corrective Date: _____						
Y _____						
Comment: _____						
CA: _____						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673713519	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3903804
673713526	Central Operating Inc Jones 1 Routine UIC	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3903799