

# Final Reclamation Inspection

07/14/2016

Operator: DJ Resources Inc

Location ID: 390645

Logan County, CO

NWSW Section 14 T10N R53W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo taken from the northwest corner of the location, facing south. Photo shows vegetation on the reclamation area.





**Figure 2:** Photo taken from the northwest corner of the location, facing southeast. Photo shows vegetation on the reclamation area.





**Figure 3:** Photo taken from the northwest corner of the location, facing east. Photo shows vegetation on the reclamation area.





**Figure 4:** Photo of starting point for the disturbance transect on location, facing east.





**Figure 5:** Photo of vegetation at the disturbance transects midpoint, facing north.





**Figure 6:** Photo of vegetation at the disturbance transects midpoint, facing south.





**Figure 7:** Photo of vegetation at the disturbance transect's midpoint





**Figure 8:** Photo of ending point for the disturbance transect, facing east.





**Figure 9:** Photo of starting point for the reference area transect.





**Figure 10:** Photo of starting point for the reference area transect, facing north.





07.14.2016 16:03

**Figure 11:** Photo of vegetation at the reference transects midpoint, facing west.





**Figure 12:** Photo of vegetation at the reference transects midpoint, facing east.





**Figure 13** Photo of vegetation at the reference transects midpoint.





**Figure 14:** Photo of ending point for the reference transect, facing south