

Final Reclamation Inspection



Photo 1. 2013 aerial imagery using COGCC GISOnline, illustrating total areas that have not been reclaimed per Rule 1004 and debris left behind.

Final Reclamation Inspection



Photo 2. Photo taken of well sign for API# 123-12244 that needs to be removed, along with fencing material and trash around wellhead.

Final Reclamation Inspection



Photo 3. Photo taken west of well sign for API# 123-12244, facing East, that needs to be removed, along with fencing material and trash around wellhead.

Final Reclamation Inspection



Photo 4. Photo taken from southwest of wellhead, facing South. Need to remove portable waste facility (i.e., trash).

Final Reclamation Inspection



Photo 5. Photo taken from west of tank battery location, facing East. Need to reclaim location per Rule 1004 (i.e., remove gravel first before seeding location).

Final Reclamation Inspection



Photo 6. Close up photo taken from the tank battery location, illustrating that gravel has not been removed per Rule 1004.

Final Reclamation Inspection



Photo 7. Photo taken from northern access road, north of tank battery location, facing South. Need to reclaim access road per Rule 1004.

Final Reclamation Inspection



Photo 8. Photo taken from southeast access road, facing West. Need to reclaim access road per Rule 1004.

Final Reclamation Inspection



Photo 9. Photo taken along access road, facing West. Need to remove debris (i.e., culverts).

Final Reclamation Inspection



Photo 10. Photo taken from western access road, facing West. Need to reclaim access road per Rule 1004.

Final Reclamation Inspection



Photo 11. Photo taken from what appears to be location entrance. Need to remove gate and fencing material per Rule 1004.