

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2016

Document Number:

675203061

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	291553	334487	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Compliance Summary:QtrQtr: NWSW Sec: 26 Twp: 9S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/12/2010	200287085	PR	PR	SATISFACTORY			No
06/19/2008	200191355	PR	PR	SATISFACTORY	I		No
08/22/2007	200121375	DG	ND	SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
290618	WELL	PR	05/16/2007	GW	077-09287	NORTH VEGA 26-221	PR	<input checked="" type="checkbox"/>
291546	WELL	PR	11/13/2012	GW	077-09361	DELTA 26-231	PR	<input checked="" type="checkbox"/>
291547	WELL	PR	07/24/2007	GW	077-09360	DELTA 26-241	PR	<input checked="" type="checkbox"/>
291548	WELL	PR	07/24/2007	GW	077-09359	DELTA 26-224	PR	<input checked="" type="checkbox"/>
291549	WELL	PR	07/24/2007	GW	077-09358	DELTA 26-141	PR	<input checked="" type="checkbox"/>
291550	WELL	PR	07/24/2007	GW	077-09357	DELTA 26-134	PR	<input checked="" type="checkbox"/>
291551	WELL	PR	07/24/2007	GW	077-09356	DELTA 26-131	PR	<input checked="" type="checkbox"/>
291552	WELL	PR	07/24/2007	GW	077-09355	DELTA 26-124	PR	<input checked="" type="checkbox"/>
291553	WELL	PR	07/24/2007	GW	077-09354	DELTA 26-121	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Equipment:

Type:	#	Satisfactory/Action Required:
Comment		
Corrective Action		Date: _____

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
METHANOL	1	500 BBLS	STEEL AST	,
S/AR	SATISFACTORY	Comment:		
Corrective Action:				Corrective Date: _____

Paint

Inspector Name: CONKLIN, CURTIS

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	400 BBLS	STEEL AST	,
S/AR	SATISFACTORY	Comment: AIRS ID 077-0498-001		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	400 BBLS	HEATED STEEL AST	,
S/AR	SATISFACTORY	Comment:		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment	Same			

Venting:

Inspector Name: CONKLIN, CURTIS

Yes/No	NO
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill			
Location ID:	291553		
Lease Road Adeq.:	Pads:	Soil Stockpile:	
S/AR:			
Corrective Action:	Date:	CDP Num.:	

Form 2A COAs:			
S/AR:	Comment:		
CA:		Date:	

Wildlife BMPs:			
S/AR:	Comment:		
CA:		Date:	

Comment:	
----------	--

Staking:

On Site Inspection (305):

<u>Surface Owner Contact Information:</u>	
Name:	Address:
Phone Number:	Cell Phone:

<u>Operator Rep. Contact Information:</u>	
Landman Name:	Phone Number:
Date Onsite Request Received:	Date of Rule 306 Consultation:

Request LGD Attendance:		
<u>LGD Contact Information:</u>		
Name:	Phone Number:	Agreed to Attend:

<u>Summary of Landowner Issues:</u>

<u>Summary of Operator Response to Landowner Issues:</u>

<u>Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:</u>

Facility									
Facility ID:	290618	Type:	WELL	API Number:	077-09287	Status:	PR	Insp. Status:	PR
Facility ID:	291546	Type:	WELL	API Number:	077-09361	Status:	PR	Insp. Status:	PR
Facility ID:	291547	Type:	WELL	API Number:	077-09360	Status:	PR	Insp. Status:	PR

Facility ID: 291548	Type: WELL	API Number: 077-09359	Status: PR	Insp. Status: PR
Facility ID: 291549	Type: WELL	API Number: 077-09358	Status: PR	Insp. Status: PR
Facility ID: 291550	Type: WELL	API Number: 077-09357	Status: PR	Insp. Status: PR
Facility ID: 291551	Type: WELL	API Number: 077-09356	Status: PR	Insp. Status: PR
Facility ID: 291552	Type: WELL	API Number: 077-09355	Status: PR	Insp. Status: PR
Facility ID: 291553	Type: WELL	API Number: 077-09354	Status: PR	Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Gravel	Pass					

Inspector Name: CONKLIN, CURTIS

Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

S/A/V: SATISFACTOR
Y Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203061	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3908483