

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
07/21/2016  
Document Number:  
674103504  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

|                     |               |               |                      |                          |             |
|---------------------|---------------|---------------|----------------------|--------------------------|-------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:      | On-Site Inspection       | 2A Doc Num: |
|                     | <u>244650</u> | <u>323019</u> | <u>Rickard, Jeff</u> | <input type="checkbox"/> |             |

**Operator Information:**

|                       |  |
|-----------------------|--|
| OGCC Operator Number: | <u>69175</u>                                     |
| Name of Operator:     | <u>PDC ENERGY INC</u>                            |
| Address:              | <u>1775 SHERMAN STREET - STE 3000</u>            |
| City:                 | <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name             | Phone          | Email                    | Comment            |
|--------------------------|----------------|--------------------------|--------------------|
| General, All inspections | (970) 332-3520 | cogccinspection@pdce.com | All PDC inspection |

**Compliance Summary:**

QtrQtr: SWSW Sec: 6 Twp: 5N Range: 66W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 05/22/2014 | 673800915 | PR         | PR          | SATISFACTORY                  | P        |                | No              |
| 01/18/2006 | 200083345 | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |
| 02/02/1997 | 500168640 | PR         | PR          |                               |          | Pass           | No              |
| 01/21/1997 | 500168639 | PR         | PR          |                               |          |                |                 |
| 12/17/1996 | 500168638 | PR         | PR          |                               |          |                |                 |
| 11/19/1996 | 500168637 | PR         | PR          |                               |          | Pass           | No              |
| 10/11/1996 | 500168636 | PR         | PR          |                               |          | Pass           | No              |
| 09/16/1996 | 500168635 | PR         | PR          |                               |          |                |                 |
| 08/15/1996 | 500168634 | PR         | PR          |                               |          |                |                 |
| 06/11/1996 | 500168633 | PR         | PR          |                               |          |                |                 |
| 05/06/1996 | 500168632 | PR         | PR          |                               |          |                |                 |
| 04/22/1996 | 500168631 | PR         | PR          |                               |          |                |                 |
| 01/25/1996 | 500168630 | PR         | PR          |                               |          | Pass           | No              |
| 01/03/1996 | 500168629 | PR         | PR          |                               |          | Pass           | No              |
| 12/04/1995 | 500168628 | PR         | PR          |                               |          | Pass           | No              |
| 11/08/1995 | 500168627 | PR         | SI          |                               |          | Pass           | No              |
| 10/04/1995 | 500168626 | PR         | PR          |                               |          | Pass           | No              |
| 09/07/1995 | 500168625 | PR         | PR          |                               |          | Pass           | No              |
| 08/22/1995 | 500168624 | PR         | PR          |                               |          | Pass           | No              |
| 07/24/1995 | 500168623 | PR         | PR          |                               |          |                |                 |
| 07/11/1995 | 500168622 | PR         | PR          |                               |          | Pass           | No              |

Inspector Name: Rickard, Jeff

|            |           |    |    |  |  |      |    |
|------------|-----------|----|----|--|--|------|----|
| 06/02/1995 | 500168621 | PR | PR |  |  | Pass | No |
| 04/11/1995 | 500168620 | PR | PR |  |  | Pass | No |
| 03/01/1995 | 500168619 | PR | PR |  |  | Pass |    |
| 02/02/1995 | 500168618 | PR | PR |  |  | Pass | No |
| 01/10/1995 | 500168617 | PR | PR |  |  |      |    |
| 01/05/1995 | 500168616 | PR | PR |  |  | Pass | No |
| 12/05/1994 | 500168615 |    | PR |  |  | Pass | No |
| 11/01/1994 | 500168614 |    | SI |  |  | Pass | No |

**Inspector Comment:**

\_\_\_\_\_

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 244650      | WELL | PR     | 06/01/2001  | GW         | 123-12445 | BRANDONDI 1   | PR          | <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

**Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
|      |                              |         |                   |      |

**Signs/Marker:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|      |                              |         |                   |         |

Emergency Contact Number (S/AR): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|      |                              |         |                   |         |

**Spills:**

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|      |      |        |                   |         |

Multiple Spills and Releases?

| <b>Fencing/:</b> |                              |         |                   |         |
|------------------|------------------------------|---------|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                  |                              |         |                   |         |

| <b>Equipment:</b> |   |                               |  |       |
|-------------------|---|-------------------------------|--|-------|
| Type:             | # | Satisfactory/Action Required: |  |       |
| Comment           |   |                               |  |       |
| Corrective Action |   |                               |  | Date: |

| <b>Venting:</b> |  |
|-----------------|--|
| Yes/No          |  |
| Comment         |  |

| <b>Flaring:</b>    |  |                              |                      |
|--------------------|--|------------------------------|----------------------|
| Type               |  | Satisfactory/Action Required |                      |
| Comment:           |  |                              |                      |
| Corrective Action: |  |                              | Correct Action Date: |

**Predrill**

Location ID: 244650

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 244650 Type: WELL API Number: 123-12445 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

|                        |                   |             |
|------------------------|-------------------|-------------|
| <b>Water Well:</b>     | Lat               | Long        |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB):   N  

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels):   YES  

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use?   Pass   Production areas stabilized ?   Pass  

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Rickard, Jeff

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| Location inventory has not changed since last inspection. | rickardj | 07/21/2016 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 674103504    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3909778">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3909778</a> |