



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing largely with intermediate wheatgrass (*Thinopyron intermedium*), crested wheatgrass (*Agropyron cristatum*), and smooth brome (*Bromus inermis*).



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4. View of the flowline equipment in the northeastern portion of the project area.



Photo 5. View of other flowline equipment in the northeastern portion of the project area.