



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of blooming musk thistles (*Carduus nutans*) in the southern portion of the project area.





Photo 3. Another view of blooming musk thistles within the interim reclamation area.





Photo 4. View of stormwater controls near the well pad entrance.