

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2016

Document Number:

680300895

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	227019	313901	SCHURE, KYM	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 518 17TH ST STE 200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
James, Steven	(303) 893-2438	s.d.james@att.net	
Stapp, Scott		scott@westernoperating.com	
Quint, Craig		craig.quint@state.co.us	

**Compliance Summary:**QtrQtr: NENE Sec: 26 Twp: 2N Range: 58W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/25/2015	680300347	IJ	IJ	SATISFACTORY			No
07/16/2013	664001114	IJ	AC	SATISFACTORY			No
07/02/2012	663400536	IJ	AC	SATISFACTORY			No
08/10/2011	200318133	RT	AC	SATISFACTORY			No
04/14/2010	200242681	RT	AC	SATISFACTORY			No
08/11/2009	200216390	RT	AC	SATISFACTORY			No
03/26/2008	200129388	MI	AC	SATISFACTORY			No
05/24/2007	200112015	RT	AC	SATISFACTORY		Pass	No
08/02/2006	200094668	RT	AC	SATISFACTORY		Pass	No
06/08/2005	200076020	RT	AC	SATISFACTORY		Pass	No
05/05/2004	200054144	RT	AC	SATISFACTORY		Pass	No
03/26/2004	200052327	RT	AC	SATISFACTORY		Pass	No
05/08/2003	200038556	RT	SI	SATISFACTORY		Pass	No
02/18/2003	200035327	MI	SI	SATISFACTORY		Pass	No

**Inspector Comment:**UIC ROUTINE INSPECTION - SATISFACTORY**Related Facilities:**

Inspector Name: SCHURE, KYM

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
159091	UIC DISPOSAL	AC	01/07/2003		-	MESSENGER 1-26	AC	<input checked="" type="checkbox"/>
227019	WELL	IJ	10/15/2011	DSPW	087-07760	MESSENGER 1-26	IJ	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type: Other	# 0	Satisfactory/Action Required: SATISFACTORY
Comment	No change in surface equipment inventoried	
Corrective Action		Date: _____

**Venting:**

Yes/No	
Comment	

**Flaring:**

Type	Satisfactory/Action Required	
Comment:		
Corrective Action:		Correct Action Date:

**Predrill**

Location ID: 227019

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: <u>159091</u>	Type: <u>UIC</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Facility ID: <u>227019</u>	Type: <u>WELL</u>	API Number: <u>087-07760</u>	Status: <u>IJ</u>	Insp. Status: <u>IJ</u>

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**Inj./Tube: Pressure or inches of Hg -1 \_\_\_\_\_  
(e.g. 30 psig or -30" Hg)Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
Inj Zone: DSND

TC: Pressure or inches of Hg 0 \_\_\_\_\_

Previous Test Pressure \_\_\_\_\_ Last MIT: 07/11/2013

Brhd: Pressure or inches of Hg \_\_\_\_\_

Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: No pressure on casing @ blow-down. Slight vacuum on tubing. Casing pressure = 0.

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_

Tbg psi: \_\_\_\_\_

Csg psi: \_\_\_\_\_

BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Inspector Name: SCHURE, KYM

S/A/V: SATISFACTOR  
Y

Corrective Date: \_\_\_\_\_

Comment: Use BMP's for stormwater erosion control and management

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT