

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2016

Document Number:

680400909

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	229809	314876	BROWNING, CHUCK	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON RD

City: RANGELY State: CO Zip: 81648

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Compliance Summary:

QtrQtr: NESW Sec: 34 Twp: 2N Range: 102W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/31/2015	680400182	IJ	AC	SATISFACTORY			No
05/21/2014	668402193	IJ	AC	SATISFACTORY	P		No
04/12/2013	668401092	IJ	AC	SATISFACTORY	P		No
05/22/2012	668400390	IJ	SI	SATISFACTORY			No
05/17/2011	200310903	RT	AC	SATISFACTORY			No
05/17/2010	200256287	RT	AC	SATISFACTORY			No
06/09/2009	200212962	RT	AC	SATISFACTORY			No
05/14/2008	200191447	MI	AC	SATISFACTORY			No
05/10/2007	200113177	RT	AC	SATISFACTORY		Pass	No
05/18/2006	200093236	RT	AC	SATISFACTORY		Pass	No
06/01/2005	200073311	RT	AC	SATISFACTORY		Pass	No
05/10/2004	200059720	RT	AC	SATISFACTORY		Pass	No
05/06/2003	200041349	MI	AC	SATISFACTORY		Pass	No
05/16/2002	200026517	RT	AC	SATISFACTORY		Pass	No
08/23/2001	200023328	PR	SI	SATISFACTORY		Pass	No
05/23/2001	200019363	RT	AC	SATISFACTORY		Pass	No
05/31/2000	200009266	RT	AC	SATISFACTORY		Pass	No
05/05/1997	500157087	PR	PR			Pass	No

Inspector Comment:

Routine UIC inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
229809	WELL	IJ	07/07/2015	ERIW	103-07466	CARNEY C T 27X- 34	AC	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action			Date: _____

Venting:

Yes/No	NO
--------	----

Comment	
---------	--

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 229809

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 229809	Type: WELL	API Number: 103-07466	Status: IJ	Insp. Status: AC
---------------------	------------	-----------------------	------------	------------------

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 1740 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: WEBR

TC: Pressure or inches of Hg 75 Previous Test Pressure _____ Last MIT: 04/12/2013

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: Routine UIC inspection. Active injection at time of inspection. Casing blowdown 60 sec.

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	SI	Pass	

Inspector Name: BROWNING, CHUCK

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680400909	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3913137