

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing North. Vegetative crop growth is below 80% of reference areas regarding crop height and density. It is hard to see in this photo but look at the highlighted area versus the further distant vegetative area.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing East. Vegetative crop growth is below 80% of reference areas regarding crop height and density. It is hard to see in this photo but look at the highlighted area versus the further distant vegetative area.