

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
07/28/2016  
Document Number:  
673803537  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

|                     |             |        |                 |   |
|---------------------|-------------|--------|-----------------|---|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection <input type="checkbox"/> |
|                     | 251623      | 330660 | Gomez, Jason    | 2A Doc Num: _____                           |

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1625 BROADWAY STE 2200  
City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
|              |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Compliance Summary:**

QtrQtr: NWSE Sec: 14 Twp: 5N Range: 67W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 12/15/2009 | 200224901 | PR         | PR          | SATISFACTORY                  | I        |                | No              |
| 07/11/2003 | 200041254 | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |

**Inspector Comment:**

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 251623      | WELL | PR     | 08/01/2003  | OW         | 123-19426 | BASS N 14-10  | PR          | <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

**Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
|      |                              |         |                   |      |

| <b>Signs/Marker:</b> |                              |         |                   |         |
|----------------------|------------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | SATISFACTORY                 |         |                   |         |
| WELLHEAD             | SATISFACTORY                 |         |                   |         |
| BATTERY              | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                              |         |                   |         |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type                      | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                           |                              |         |                   |         |

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |          |                   |         |
|------------------|------------------------------|----------|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment  | Corrective Action | CA Date |
| TANK BATTERY     | SATISFACTORY                 | WIRE     |                   |         |
| WELLHEAD         | SATISFACTORY                 | AG PANEL |                   |         |
| SEPARATOR        | SATISFACTORY                 | WIRE     |                   |         |

| <b>Equipment:</b>                 |     |                               |              |       |
|-----------------------------------|-----|-------------------------------|--------------|-------|
| Type: Bird Protectors             | # 8 | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           |     |                               |              |       |
| Corrective Action                 |     |                               |              | Date: |
| Type: Gas Meter Run               | # 4 | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           |     |                               |              |       |
| Corrective Action                 |     |                               |              | Date: |
| Type: Emission Control Device     | # 3 | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           |     |                               |              |       |
| Corrective Action                 |     |                               |              | Date: |
| Type: Plunger Lift                | # 1 | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           |     |                               |              |       |
| Corrective Action                 |     |                               |              | Date: |
| Type: Horizontal Heated Separator | # 5 | Satisfactory/Action Required: | SATISFACTORY |       |
| Comment                           |     |                               |              |       |
| Corrective Action                 |     |                               |              | Date: |

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Inspector Name: Gomez, Jason

|                    |              |           |                     |                       |
|--------------------|--------------|-----------|---------------------|-----------------------|
| Contents           | #            | Capacity  | Type                | SE GPS                |
| PRODUCED WATER     | 5            | <100 BBLS | CONCRETE SUMP/VAULT | 40.396610,-104.860050 |
| S/AR               | SATISFACTORY |           | Comment:            |                       |
| Corrective Action: |              |           |                     | Corrective Date:      |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  | _____    |
| Other (Capacity) | _____    |
| Other (Type)     | _____    |

**Berms**

|                   |          |                     |                     |                 |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type              | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance     |
| Earth             | Adequate | Walls Sufficient    | Base Sufficient     | Adequate        |
| Corrective Action |          |                     |                     | Corrective Date |
| Comment           |          |                     |                     |                 |

**Facilities:**       New Tank      Tank ID: \_\_\_\_\_

|                    |              |          |           |                       |
|--------------------|--------------|----------|-----------|-----------------------|
| Contents           | #            | Capacity | Type      | SE GPS                |
| CRUDE OIL          | 6            | 300 BBLS | STEEL AST | 40.396610,-104.860050 |
| S/AR               | SATISFACTORY |          | Comment:  |                       |
| Corrective Action: |              |          |           | Corrective Date:      |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  | _____    |
| Other (Capacity) | _____    |
| Other (Type)     | _____    |

**Berms**

|                   |          |                     |                     |                 |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type              | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance     |
| Earth             | Adequate | Walls Sufficient    | Base Sufficient     | Adequate        |
| Corrective Action |          |                     |                     | Corrective Date |
| Comment           |          |                     |                     |                 |

**Venting:**

|         |       |
|---------|-------|
| Yes/No  | NO    |
| Comment | _____ |

**Flaring:**

|                    |                              |  |                      |
|--------------------|------------------------------|--|----------------------|
| Type               | Satisfactory/Action Required |  |                      |
| Comment:           | _____                        |  |                      |
| Corrective Action: |                              |  | Correct Action Date: |

**Predrill**

Location ID: 251623

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 251623 Type: WELL API Number: 123-19426 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: PLUMBED TO SURFACE

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): Y  
 Comment: \_\_\_\_\_  
 Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**  
 Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
 Land Use: \_\_\_\_\_  
 Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

**RESTORATION AND REVEGETATION**  
Cropland  
 Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_  
Non-Cropland

Inspector Name: Gomez, Jason

Top soil replaced Pass

Recontoured Pass

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location

Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 673803537    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3914806">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3914806</a> |