

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/28/2016

Document Number:

673803546

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 332941      | 332941 | Gomez, Jason    | <input type="checkbox"/> |             |

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone | Email                                  | Comment |
|--------------|-------|--|---------|
|              |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Compliance Summary:**QtrQtr: CNE Sec: 14 Twp: 5N Range: 67W**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 280872      | WELL | PR     | 05/13/2011  | OW         | 123-23316 | RAGAN N 14-17 | PR          | <input checked="" type="checkbox"/> |
| 280890      | WELL | PR     | 09/13/2014  | OW         | 123-23317 | RAGAN N 14-1  | PR          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location****Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
|      |                              |         |                   |      |

Inspector Name: Gomez, Jason

| <b>Signs/Marker:</b> |                              |         |                   |         |
|----------------------|------------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 |         |                   |         |
| WELLHEAD             | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                              |         |                   |         |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type                      | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                           |                              |         |                   |         |

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |          |                   |         |
|------------------|------------------------------|----------|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment  | Corrective Action | CA Date |
| WELLHEAD         | SATISFACTORY                 | AG PANEL |                   |         |
| WELLHEAD         | SATISFACTORY                 | AG PANEL |                   |         |

| <b>Equipment:</b>  |     |  |  |       |
|--------------------|-----|--|--|-------|
| Type: Plunger Lift | # 2 | Satisfactory/Action Required: SATISFACTORY |  |       |
| Comment            |     |  |  |       |
| Corrective Action  |     |  |  | Date: |

| <b>Facilities:</b>                |   |                |                     |                  |
|-----------------------------------|---|----------------|---------------------|------------------|
| <input type="checkbox"/> New Tank |   | Tank ID: _____ |                     |                  |
| Contents                          | # | Capacity       | Type                | SE GPS           |
|                                   |   |                | CENTRALIZED BATTERY | ,                |
| S/AR                              |   | Comment:       | API 05-123-29725    |                  |
| Corrective Action:                |   |                |                     | Corrective Date: |

Paint

|           |  |
|-----------|--|
| Condition |  |
|-----------|--|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

|                   |  |                 |  |
|-------------------|--|-----------------|--|
| Corrective Action |  | Corrective Date |  |
| Comment           |  |                 |  |

| <b>Venting:</b> |    |
|-----------------|----|
| Yes/No          | NO |

Comment

**Flaring:**

|                    |                              |                      |  |
|--------------------|------------------------------|----------------------|--|
| Type               | Satisfactory/Action Required |                      |  |
| Comment:           |                              |                      |  |
| Corrective Action: |                              | Correct Action Date: |  |

**Predrill**

Location ID: 332941

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 280872 Type: WELL API Number: 123-23316 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Inspector Name: Gomez, Jason

**BradenHead**

Comment: **PLUMBED TO SURFACE**

CA:

CA Date:

Facility ID: 280890 Type: WELL API Number: 123-23317 Status: PR Insp. Status: PR

**Producing Well**

Comment: **PR**

**BradenHead**

Comment: **PLUMBED TO SURFACE**

CA:

CA Date:

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

DWR Receipt Num: Owner Name: GPS: Lat Long

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Waste and Debris removed? Pass

CM

CA CA Date

Unused or unneeded equipment onsite? Pass

CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Pass

Inspector Name: Gomez, Jason

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

#### **Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Inspector Name: Gomez, Jason

S/A/V: SATISFACTOR

Corrective Date: \_\_\_\_\_

Y

Comment: **VEGETATION RE-GROWTH**

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 673803546    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3914814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3914814</a> |