

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2016

Document Number:

674602716

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	243284	319329	Maclaren, Joe	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 39560Name of Operator: TOP OPERATING COMPANYAddress: 3609 S WADSWORTH BLVD STE 340City: LAKEWOOD State: CO Zip: 80235

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Herring, Paul	303-727-9915	paul.herring@topoperating.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hazard, Ellice		ellice.hazard@state.co.us	

Compliance Summary:QtrQtr: SESW Sec: 6 Twp: 2N Range: 68W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/10/2015	680700042	PR	PR	SATISFACTORY			No
03/20/2015	670900401	PR	PR	ACTION REQUIRED			No
03/15/2013	670500553	PR	SI	ALLEGED VIOLATION	P		Yes
04/16/2007	200111480	PR	PR	ACTION REQUIRED		Pass	No
06/13/1996	500166534	PR	PR			Fail	Yes

Inspector Comment:

Engineering Integrity inspection conducted with a primary focus on the flowlines at this well site. The Actions Required identified are located in the housekeeping/ weeds section of this report. Please also note the comments located at the end of this report. Photo's uploaded can be accessed via link(s) at end of report.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
243284	WELL	PR	02/25/2014	GW	123-11075	MAYEDA, JOHN Y. 2	EG	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: Maclaren, Joe

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	Uncontrolled weed growth observed around equipment, inside tank berms and wellhead.	Remove weeds/ Control future growth.	08/29/2016

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type: Flow Line	#	Satisfactory/Action Required:
Comment	Approximate orientations of well site and dump flowlines identified. No integrity issues observed at the time of this field inspection.	
Corrective Action	Date:	

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS

S/AR: _____ Comment: _____

Corrective Action: _____ Corrective Date: _____

Inspector Name: Maclaren, Joe

Paint Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Corrective Action					Corrective Date
Comment	Repair and maintain berm damage from prairie dogs.				

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 243284

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 243284 Type: WELL API Number: 123-11075 Status: PR Insp. Status: EG

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Inspector Name: Maclaren, Joe

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: Maclaren, Joe

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
1101e. Pressure testing of flowlines. (1) Before operating a segment of flowline it shall be tested to maximum anticipated operating pressure. In conducting tests, each operator shall ensure that reasonable precautions are taken to protect its employees and the general public. The testing may be conducted using well head pressure sources and well bore fluids, including natural gas. Such pressure tests shall be repeated once each calendar year to maximum anticipated operating pressure, and operators shall maintain records of such testing for Commission inspection for at least three (3) years. (2) Flowline segments operating at less than fifteen (15) psig are excepted from pressure testing requirements.	maclarej	07/29/2016
Note: Future contact will be made with operator by COGCC Engineering Integrity staff to discuss COGCC series 1100 (flowline) rules; with an emphasis on 1101e. annual flowline pressure testing requirements.	maclarej	07/29/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674602722	Battery, signage & weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916216
674602723	Treater - Weeds at equipment and sides of location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916217
674602724	Weeds at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3916218

