


Grassy Creek Coal Co 1-24

Inspection# 673403454

Erosion gully leaving location on western edge.



Potential pit located on western edge of location.



Pit located immediately adjacent to wellhead on south.



Potential pit located on south behind pit in above photo.



Rat hole.



Casing leak.

