

Final Reclamation Inspection



Photo 1. Photo taken from southern tank battery location, facing West. Mostly Kochia sp. throughout tank battery. There is a 5'x5' patch of Canada thistle just west of the separator.

Final Reclamation Inspection



Photo 2. Photo taken from well location, facing West. High density of Kochia sp. and Canada thistle throughout location, along with debris.

Final Reclamation Inspection



Photo 3. Photo taken from well location, facing South. High density of Kochia sp. and Canada thistle throughout location, along with debris.

Final Reclamation Inspection



Photo 4. Photo taken from the southern well location, facing South. Canada thistle has moved into the adjacent corn field.