

# Timpe Reclamation Follow-up

08/03/2016

Location ID: 393754

Morgan County, CO

NENW Section 6 T1N R56W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo taken from CR F at access road entrance/gate, facing north. Areas appears to see heavy livestock use.



**Figure 2:** Photo taken from ranch two-track just north of the access gate on County Road F, facing south. Straw crimped into soil appears to be holding.



**Figure 3:** Photo taken from ranch two-track just north of the access gate on County Road F, facing west.



**Figure 4:** Photo of access road.



**Figure 5:** Ranch two-track where road turns west.



**Figure 6:** Ranch two-track where road turns west.



**Figure 7:** Ranch two-track where road turns north. Area has seen heavy livestock use, crimped straw appears to be holding.



**Figure 8:** Ranch two-track where road turns north. Area has seen heavy livestock use, crimped straw appears to be holding.



**Figure 9:** Photo taken from fenceline, east of the location, facing east. Photo shows access road and reclamation in process.



**Figure 10:** Photo taken from fenceline, east of the location, facing west. Photo shows access road and reclamation in process.



**Figure 11:** Photo taken from access road, east of location. Photo shows some weedy species have grown on the disturbed areas, however, species such as *Andropogon hallii* and *Sporobolus cryptandrus* from our seed mix is also present.



**Figure 12:** Photo taken from access road east of location. Photo shows *Artemisia filifolia* that had been disturbed from our reclamation activities is recovering.



**Figure 13:** Photo taken from the southeast corner of the location, facing west. Photo shows corn has germinated within the project area.



**Figure 14:** Photo taken from the southeast corner of the location, facing west. Photo shows corn has germinated within the project area.



**Figure 15:** Photo of vegetation within the reclamation area. Photo *Amaranthus* species may have been brought in with the mulch.



**Figure 16:** Photo taken approximately 100 yards southwest of location, facing west. Photo of reclamation in process.



**Figure 17:** Photo taken approximately 100 yards southwest of location, facing west. Photo of reclamation in process.



**Figure 18:** Photo taken approximately 100 yards southwest of location, facing east towards the location. Photo of reclamation in process.