

Interim Reclamation Inspection



Photo 1. Photo taken of PR well sign for API #123-31153.

Interim Reclamation Inspection




Photo 2. Photo taken from well location, facing West. Crop growth is stunted and crop density is diminished or not growing which is not reflective of reference areas. Crop height in interim areas averaged 24" versus 84" in reference areas.

Interim Reclamation Inspection



Photo 3. Photo taken from eastern location, facing West, illustrating discrepancy between reference and interim areas. Interim area density and height not representative of reference area.

Interim Reclamation Inspection



Photo 4. Photo taken from eastern location, facing South, illustrating areas with no crop growth.

Interim Reclamation Inspection



Photo 5. Photo taken from northeast location, facing West, illustrating areas with no crop growth and/or stunted crop growth.