

Final Reclamation Inspection

06/28/2016

Operator: Petro-Canada

Location ID: 376781

Adams County, CO

NENW Section 24 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: 1933 Aerial imagery showing location of Pit, facilities and well.




Figure 2: 9/6/2013 aerial imagery of location. Note area of salt kill below (east) area of pit. Sundry doc 2172955 submitted in 2012 stated reclamation complete.



Figure 3: Photo taken from the east end of the pit area, facing northeast. Photo shows fenced off, salt kill area from figure 2.



Figure 4: Photo taken from the fenced area on the north end of the location, facing north. Photo shows vegetation on location has not achieved uniform distribution. Possible salt kill remains.



Figure 5: Photo taken from the fenced area on the north end of the location, facing north. Photo shows areas of possible salt kill still remaining within the fenced remediation area.



Figure 6: Photo taken from the northwest corner of the well location, facing south. Photo shows interim reclamation areas appear to be adequately vegetated.



Figure 7: Photo taken from the site of the well, facing north. Photo shows the well location has not achieved uniform perennial vegetative cover. Plants seen are predominantly annual *Thlaspi arvense*



06.28.2016 12:30

Figure 8: Photo taken from the access road on the west end of the well location, facing west. Photo shows access road has not been recontoured.



Figure 9: Photo taken from the access road, southwest of the location, facing west. Photo shows access road had not been recontoured.



Figure 10: Photo taken from the access road, southwest of the location, facing northwest. Photo shows access road had not been recontoured.



Figure 11: Photo taken from the access road, southwest of the location, facing north. Photo shows access road had not been recontoured.