

# Final Reclamation Inspection

06/28/2016

Operator: Petro-Canada

Location ID: 375675

Adams County, CO

NESE Section 23 T3S R59W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** 1933 Aerial imagery showing location of Pit, facilities and well. Note the two large areas of degradation



**Figure 2:** 9/6/2013 aerial imagery of location. Note areas of degradation (southern and northern), and an area that has been fenced off



**Figure 3:** Photo taken from the well location, facing south. Photo shows well location has not achieved uniform vegetative cover. 6' measuring stick for reference.



**Figure 4:** Photo taken from the well location, facing east. Photo shows well location has not achieved uniform vegetative cover.



**Figure 5:** Photo taken from the well location, facing west. Photo shows well location has not achieved uniform vegetative cover.



**Figure 6:** Photo taken from the facility/battery area of the location, facing east. Photo shows vegetation appears to be progressing towards reclamation requirements over this portion of the location.



**Figure 7:** Photo taken from the facility/battery area of the location, facing south. Photo shows vegetation appears to be progressing towards reclamation requirements over this portion of the location.



06.28.2016 13:50

**Figure 8:** Photo taken from the northwest corner of the pit location, facing southwest. Photo shows remediation area has been fenced off and terraced.



**Figure 9:** Photo taken from the northwest corner of the pit location, facing south. Photo shows remediation area has been fenced off and terraced.



**Figure 10:** Photo taken from within the fenced remediation area. Photo shows remediation has not achieved uniform vegetative cover per reclamation regulations.



**Figure 11:** Photo taken from within the fenced remediation area. Photo shows remediation has not achieved uniform vegetative cover per reclamation regulations. 6' measuring stick for reference.



**Figure 12:** Photo taken from within the fenced remediation area. Photo shows remediation has not achieved uniform vegetative cover per reclamation regulations. 6' measuring stick for reference.