

Construction Inspection

08/01/2016

Operator: Grand Mesa

Location ID: 445661

Washington County, CO

NESW Section 18 T5S R53W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from CR U, west of the location, facing east. Photo shows area vehicles have used to access location. Likely to be where access road will be constructed.



Figure 2: Photo taken from the southwest corner of the location, facing north. Photo shows stormwater and sediment control ditch on the western perimeter.



Figure 3: Photo taken from the southwest corner of the location, facing east. Photo shows stormwater and sediment control ditch on the eastern perimeter.



Figure 4: Photo taken from the southeast corner of the location, facing west. Photo shows stormwater and sediment control ditch on the southern perimeter.



Figure 5: Photo taken from the southeast corner of the location, facing north. Photo shows stormwater and sediment control ditch on the eastern perimeter..



Figure 6: Photo taken from the east end of the location, facing north. Photo shows stormwater and sediment control BMP incomplete on the eastern perimeter.



Figure 7: Photo taken from the east end of the location, facing northwest. Photo shows stormwater and sediment control BMPs absent from the northeast end of the location.



Figure 8: Photo taken from the northeast corner of the location, facing south. Photo shows stormwater and sediment control BMPs absent.



Figure 9: Photo taken from the northeast corner of the location, facing west. Photo shows stormwater and sediment control BMPs absent from north end of the location.



Figure 10: Photo taken from the northwest corner of the location, facing east. Photo shows stormwater and sediment control BMPs absent from north end of the location.



Figure 11: Photo taken from the northwest corner of the location, facing south. Photo shows stormwater and sediment control BMP incomplete on the western perimeter.