

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2016

Document Number:

681901271

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	241196	318383	HELGELAND, GARY	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	303-825-4822	cogcc@kpk.com	VP OF ENGINEER

Compliance Summary:QtrQtr: SWNW Sec: 13 Twp: 1N Range: 68W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/24/2011	200304968	PR	PR	ACTION REQUIRED			Yes
07/05/2002	200028329	PR	TA	ACTION REQUIRED		Fail	Yes
04/13/1998	500163715	ID	TA			Fail	Yes
01/17/1996	500163714	ID	TA			Fail	Yes

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
241196	WELL	PR	12/13/2000	GW	123-08984	UPRR 43 PAN AM I 25	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	NONE		

Equipment:

Type: Other # 1 Satisfactory/Action Required: SATISFACTORY

Comment: WELL WITH NO PUMPJACK.

Corrective Action: _____ Date: _____

Tanks and Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS

S/AR: _____ Comment: Refer to inspection # 681901270 for information concerning shared battery and equipment.

Corrective Action: _____ Corrective Date: _____

Paint

Condition: _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action: _____ Corrective Date: _____

Comment: _____

Venting:

Yes/No: NO

Comment: _____

Flaring:

Type	Satisfactory/Action Required
Comment: _____	

Corrective Action:

Correct Action
Date:**Predrill**

Location ID: 241196

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:_____

_____Summary of Operator Response to Landowner Issues:_____

_____Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:_____

_____**Facility**

Facility ID: 241196 Type: WELL API Number: 123-08984 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is not plumed to surface for pressure monitoring.

CA: Plumb bradenhead to surface.

CA Date: 09/09/2016

Environmental**Spills/Releases:**

Inspector Name: HELGELAND, GARY

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): <u>Y</u>
Comment: _____
Pilot: <u>ON</u> Wildlife Protection Devices (fired vessels): <u>YES</u>

Reclamation - Storm Water - Pit

Interim Reclamation:	
Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: _____	

1003a. Waste and Debris removed? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____	
CM _____	
CA _____	CA Date _____

1003b. Area no longer in use? _____	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? <u>Pass</u>	Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: HELGELAND, GARY

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass

Recontoured Pass

80% Revegetation In

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

S/A/V: SATISFACTORY Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681901272	WELL	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3924444