

Photo#1:

View North over Location



Photo#2:

View South over Location



Photo#3:
View East over Location



Photo#4:
View West over Location



Photo#5:
Concrete Debris on Location



Photo#6:



Photo#7:

Associated Facilities and Debris remain on Location.



Photo#8:



Photo# 9:
Un-reclaimed Facilities / Debris to North of Location



August 2, 2016

Inspection Photos: Kirby-Edison #1-A,
API#103-07658