

Reclamation Inspection

08/11/2016

Operator: Houston Exploration Co

Location ID: 411450

Yuma County, CO

NENW Section 5 T3N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from the southeast end of the location. Photo shows areas of access road leading into the location remains largely unvegetated.



Figure 2: Photo of the starting point for the disturbance transect, facing north.



Figure 3: Photo taken from the 50th point of the disturbance transect, facing east.



Figure 4: Photo taken from the 50th point of the disturbance transect, facing west.



Figure 5: Photo taken from the 50th point of the disturbance transect.



Figure 6: Photo of the end point for the disturbance transect, facing south.



Figure 7: Photo shows gravel/aggregate remaining on location.



Figure 8: Photo shows native Valent sand soil.



Figure 9: Photo of the starting point for the reference transect, facing southeast.



Figure 10: Photo taken from the 50th point of the reference transect, facing northeast



Figure 11: Photo taken from the 50th point of the reference transect, facing southwest.



Figure 12: Photo taken from the 50th point of the reference transect.



Figure 13: Photo of the end point for the reference transect, facing northwest.