

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/11/2016

Document Number:

682501175

Overall Inspection:

**ACTION REQUIRED****FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 411450      | 411450 | Trujillo, Aaron | <input type="checkbox"/> |             |

**Operator Information:**OGCC Operator Number: 10068Name of Operator: HOUSTON EXPLORATION COMPANY\* THEAddress: 1415 LOUISIANA STREET #1600City: HOUSTON State: TX Zip: 77002☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN  
CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

| Contact Name    | Phone | Email                   | Comment         |
|-----------------|-------|-------------------------|-----------------|
| Sumrall, Dianne |       | dsumrall@sabineoil.com  | All Inspections |
| Ramos, Martha   |       | martha.amos@state.co.us |                 |

**Compliance Summary:**QtrQtr: NENW Sec: 5 Twp: 3N Range: 43W**Inspector Comment:**

This is a final reclamation and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|-------------------------------------|
| 275492      | WELL | PA     | 01/30/2005  | DA         | 125-09053 | BLEDSE 3-5-3-43 | RI          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

|                             |                        |                     |                         |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____     | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____  | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____      | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____      | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

Emergency Contact Number (S/AR): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

**Venting:**

Yes/No

Comment

**Flaring:**

Type

Satisfactory/Action Required

Comment:

Corrective Action:

Correct Action  
Date:**Predrill**

Location ID: 411450

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 275492 Type: WELL API Number: 125-09053 Status: PA Insp. Status: RI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Inspector Name: Trujillo, Aaron

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: **Rangeland, valent sand hills**

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed **Fail** No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: **This location does not meet reclamation regulations; insufficient vegetative cover. Transects were conducted indicating vegetation is not 80% of the surrounding reference area. SEE ATTACHED DATA RESULTS AND PHOTOS**

Corrective Action: **Remove gravel, establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture that matches the adjacent pastureland or a seed mixture requested by the landowner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be complete no later than 11/15/2016**

Date **11/15/2016**

Overall Final Reclamation **Fail** Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 682501175    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3927230">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3927230</a> |
| 682501176    | Transect Data Sheet | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3927211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3927211</a> |

|           |                   |   |
|-----------|-------------------|---|
| 682501177 | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3927212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3927212</a> |
|-----------|-------------------|---|