

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2016

Document Number:

680000577

Overall Inspection:

SATISFACTORY w/ CMT
or AR**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 227888 | 314193 | QUINT, CRAIG | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 8005Name of Operator: BERRY ENERGY INC*WALTERAddress: 1717 WASHINGTON AVECity: GOLDEN State: CO Zip: 80401-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|---------|
| Whiting, Jim | 719-688-0064 | jimwhiting_99@yahoo.com | |
| Cruson, Michael | (303) 279-0190 | mcruson@berryenergyinc.com | |

Compliance Summary:QtrQtr: SENE Sec: 22 Twp: 22S Range: 45W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|------------|----------------|-----------------|
| 02/09/2016 | 680000388 | PA | PA | AR | | Fail | No |
| 02/12/2013 | 668600354 | PA | PA | ACTION REQUIRED | | In Process | No |
| 01/13/2010 | 200227064 | SR | PA | ACTION REQUIRED | | | No |
| 12/30/2009 | 200226008 | SR | PA | ACTION REQUIRED | | | No |
| 12/21/2007 | 200123937 | CA | SI | SATISFACTORY | | | No |
| 12/19/2007 | 200123938 | CA | SI | SATISFACTORY | | | No |
| 12/05/2007 | 200123152 | ID | SI | ACTION REQUIRED | | | Yes |
| 03/10/2000 | 200005140 | PR | PR | SATISFACTORY | In Process | Pass | No |
| 09/22/1997 | 500156436 | ES | PR | | | Pass | No |
| 05/07/1997 | 500156431 | PR | PR | | | Fail | Yes |
| 09/01/1994 | 500156430 | | SI | | | | Yes |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 102524 | PIT | CL | 09/23/1999 | | - | PRAIRIE DOG 1 | CL |
| 227888 | WELL | PA | 12/21/2007 | GW | 099-06215 | PRAIRIE DOG 1 | PA |

Equipment:Location Inventory

Inspector Name: QUINT, CRAIG

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Venting:

| | |
|--------|--|
| Yes/No | |
|--------|--|

| | |
|---------|--|
| Comment | |
|---------|--|

Flaring:

| | | | |
|------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
|------|--|------------------------------|--|

| | |
|----------|--|
| Comment: | |
|----------|--|

| | | | |
|--------------------|--|----------------------|--|
| Corrective Action: | | Correct Action Date: | |
|--------------------|--|----------------------|--|

Predrill

Location ID: 227888

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 227888 Type: WELL API Number: 099-06215 Status: PA Insp. Status: PA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: QUINT, CRAIG

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured _____

Compaction alleviation In Dust and erosion control In

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present Pass Subsidence Pass

Comment: Wellhead has been cut, capped and covered, equipment has been removed, Pipeline riser still in place is a shut off and is active.

Corrective Action: Decomcompact location and access, seed as needed and reclaim location. A final reclamation inspection will be performed by a Reclamation Specialist.

Date 02/15/2017

Overall Final Reclamation In Process Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 680000577 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3928088 |