

Final Reclamation Inspection



Photo 1. Photo taken from entrance of location off County Line Road. Need to remove sign.

Final Reclamation Inspection



Photo 2. Photo taken from entrance of location, facing East. Access road has not been reclaimed per Rule 1004. Also, List B Noxious weeds exist throughout access road and location which need to be removed per Rule 1004.

Final Reclamation Inspection



Photo 3. Photo taken from approximate center of location, facing East. Location has not been reclaimed per Rule 1004.

Final Reclamation Inspection



Photo 4. Electrical service panel needs to be removed from location.

Final Reclamation Inspection



Photo 5. Photo taken of a List B noxious weed species, Diffuse knapweed (*Centaurea diffusa*), which is found along the access road and location, and needs to be removed per Rule 1004.

Final Reclamation Inspection



Photo 6. Photo taken of a List B noxious weed species, Spotted knapweed (*Centaurea stoebe*), which is found along the access road and location, and needs to be removed per Rule 1004.

Final Reclamation Inspection



Photo 7. Photo taken of Diffuse and Spotted knapweed along the access road.

Final Reclamation Inspection



Photo 8. Reference photo taken from west of location, facing North. Location is not reflective of reference areas and noxious weeds are present throughout access road and location.