

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/15/2016
Document Number:
680400999
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>229116</u>	<u>314603</u>	<u>BROWNING, CHUCK</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>16700</u>
Name of Operator:	<u>CHEVRON USA INC</u>
Address:	<u>100 CHEVRON RD</u>
City:	<u>RANGELY</u> State: <u>CO</u> Zip: <u>81648</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Compliance Summary:

QtrQtr: SWNE Sec: 26 Twp: 2N Range: 102W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/15/2015	680400057	SI	AC	SATISFACTORY			No
05/21/2014	668402206	SI	AC	SATISFACTORY	Pass		No
08/14/2013	668401576	SI	AC	SATISFACTORY	Pass		No
05/20/2013	668401190	SI	AC	SATISFACTORY	Pass		No
05/21/2012	662300549	SI	AC	SATISFACTORY			No
05/19/2011	200310916	RT	AC	SATISFACTORY			No
05/17/2010	200256338	RT	AC	SATISFACTORY			No
06/09/2009	200213087	RT	AC	SATISFACTORY			No
12/11/2008	200200012	RT	AC	SATISFACTORY			No
05/10/2006	200092488	MI	AC	ACTION REQUIRED		Fail	Yes
06/01/2005	200072772	RT	AC	SATISFACTORY		Pass	No
05/11/2004	200056712	RT	AC	SATISFACTORY		Pass	No
05/21/2003	200043463	RT	AC	SATISFACTORY		Pass	No
05/16/2002	200027458	RT	AC	SATISFACTORY		Pass	No
05/16/2001	200018637	MI	SI	SATISFACTORY		Pass	No
07/31/2000	200009025	RT	SI	SATISFACTORY		Pass	No
09/24/1997	500156850						

Inspector Comment:

Routine UIC inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
229116	WELL	SI	12/20/2000	ERIW	103-06199	LEVISON 14	AC	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	NO
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 229116

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 229116 Type: WELL API Number: 103-06199 Status: SI Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 1580
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____

MPP _____

Inj Zone: WEBR

TC: Pressure or inches of Hg 0

Previous Test Pressure _____

Last MIT: 08/14/2013

Brhd: Pressure or inches of Hg 0

Previous Test Pressure _____

AnnMTRReq: _____

Comment: Routine UIC inspection. Active injection at time of inspection. Casing blowdown 0 sec.

Method of Injection: PUMP FEED

Test Type: _____

Tbg psi: _____

Csg psi: _____

BH psi: _____

Insp. Status: _____

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? Pass
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	Self Inspection	Pass	

Inspector Name: BROWNING, CHUCK

S/A/V: SATISFACTORY Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT