

Construction Inspection

08/15/2016

Operator: Whiting

Location ID: 445049

Weld County, CO

Lot 2 Section 30 T10N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from the southeast corner of the location, facing west. Photo shows stormwater and sediment control ditch BMP on the southern perimeter of the location.



Figure 2: Photo taken from the southeast corner of the location, facing north. Photo shows stormwater and sediment control BMPs missing partially on the eastern perimeter of the location and topsoil stockpile.



Figure 3: Photo taken from the east end of the location, facing north. Photo shows stormwater and sediment control ditch BMP only partially on the eastern perimeter of the location.



Figure 4: Photo taken from the northeast corner of the location, facing south. Photo shows stormwater and sediment control ditch BMP on the (partial) eastern perimeter of the location.



Figure 5: Photo taken from the northeast corner of the location, facing west. Photo shows stormwater and sediment control ditch BMP on the northern perimeter of the location.



Figure 6: Photo taken from the northwest corner of the location, facing east. Photo shows stormwater and sediment control ditch BMP on the northern perimeter of the location.



Figure 7: Photo taken from the northwest corner of the location, facing west. Photo shows stormwater and sediment control ditch BMP on the northern perimeter of the location.



Figure 8: Photo taken from the northwest corner of the location, facing south. Photo shows stormwater and sediment control ditch BMP on the western perimeter of the location.



Figure 9: Photo taken from the northwest corner of the location, facing east. Photo shows stormwater and sediment control ditch BMP on the northern perimeter of the location.



Figure 10: Photo taken from the southwest corner of the location, facing east. Photo shows stormwater and sediment control ditch BMP on the southern perimeter of the location.



Figure 11: Photo taken from the southwest corner of the location, facing north. Photo shows stormwater and sediment control ditch BMP on the western perimeter of the location.