

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2016

Document Number:

685301097

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	261384	326651	St John, William (Cal)	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports

**Compliance Summary:**QtrQtr: NESW Sec: 20 Twp: 35N Range: 7W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/02/2016	685300082	PR	PR	SATISFACTORY			No
08/25/2015	680600089	PR	PR	ACTION REQUIRED	Fail		No
11/14/2012	669400254	PR	PR	SATISFACTORY	In Process		No
03/06/2012	661700163	PR	PR	SATISFACTORY			No
04/16/2009	200208717	PR	PR	SATISFACTORY			No
08/08/2006	200101676	PR	PR	SATISFACTORY		Pass	No
12/29/2004	200066294	PR	PR	SATISFACTORY		Pass	No
08/20/2002	200030961	ID	SI	SATISFACTORY		Pass	No

**Inspector Comment:**Inspection conducted as part of monitoring of Frac Operation.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
261384	WELL	PR	04/11/2002	GW	067-08630	CUNDIFF FEDERAL A 2	WO	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Inspector Name: St John, William (Cal)

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

#### Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
SEPARATOR	SATISFACTORY	Panel - Includes Produced Water Tank.		

#### Equipment:

Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment	Wellhead		
Corrective Action	Date:		
Type: Bird Protectors	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		
Type: Flow Line	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date:		

Inspector Name: St John, William (Cal)

Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:

**Tanks and Berms:**

☐ New Tank

Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL	,

S/AR	SATISFACTORY	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

**Venting:**

Yes/No	NO
Comment	

**Flaring:**

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 261384

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 261384 Type: WELL API Number: 067-08630 Status: PR Insp. Status: WO

**Well Stimulation**

Stimulation Company: Halliburton

Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: 2840 PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) 4750

Bradenhead Psi: 4

Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: St John, William (Cal)

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

**Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Inspector Name: St John, William (Cal)

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass					
Compaction	Pass	Gravel	Pass			

S/A/V: SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685301097	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3929467">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3929467</a>