

Reclamation Inspection

08/15/2016

Operator: Diversified Operating Corp

Location ID: 409213

Weld County, CO

SESW Section 21 T8N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo GPS confirming location.



Figure 2: Photo taken from location. Photo shows large bare area on location. Photo shows large bare areas on location that remain unvegetated. These areas need to be reclaimed.



Figure 3: Photo taken from location, facing northwest. Photo shows large bare areas on location that remain unvegetated. These areas need to be reclaimed.



Figure 4: Photo taken from location. Photo shows large bare area on location. Photo shows large bare areas on location that remain unvegetated. These areas need to be reclaimed.



Figure 5: Photo taken from location. Photo shows large bare area on location. Photo shows large bare areas on location that remain unvegetated. These areas need to be reclaimed.



Figure 6: 1998 Aerial imagery of location and access road.




Figure 7: 2013 Aerial imagery of location and access road. Note arrow identifies area where gully along access road exists.