

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2016

Document Number:

674703038

Overall Inspection:

SATISFACTORY w/ CMT
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335842	335842	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10516Name of Operator: LINN OPERATING INCAddress: 600 TRAVIS STREET #5100City: HOUSTON State: TX Zip: 77002

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	
Burns, Bryan		bburns@linnenergy.com	
White, Brent		bwhite@linnenergy.com	Production Foreman
Foster, Michael	281-840-4375	MFoster@linnenergy.com	Regulatory Compliance Specialist II
Johnson, Derek	970-285-2200	dsjohnson@linnenergy.com	

Compliance Summary:QtrQtr: NWNW Sec: 32 Twp: 5S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/28/2015	674701985			SATISFACTORY			No
05/28/2015	674701459			SATISFACTORY			No
08/13/2014	671000049			ACTION REQUIRED			No
06/26/2013	663801184			SATISFACTORY	In Process		No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
289226	WELL	PR	10/06/2009	GW	045-13693	LATHAM 32-24D	PR	<input checked="" type="checkbox"/>
289227	WELL	PR	10/06/2009	GW	045-13692	LATHAM 32-23D	PR	<input checked="" type="checkbox"/>
289228	WELL	PR	11/06/2009	GW	045-13691	LATHAM 32-22D	PR	<input checked="" type="checkbox"/>
289229	WELL	PR	10/30/2009	GW	045-13690	LATHAM 32-29D	PR	<input checked="" type="checkbox"/>
289230	WELL	PR	05/01/2015	GW	045-13689	LATHAM 32-30D	PR	<input checked="" type="checkbox"/>
289231	WELL	PR	10/30/2009	GW	045-13688	LATHAM 32-31D	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

289232	WELL	PR	02/13/2012	GW	045-13687	LATHAM 32-32D	PR	<input checked="" type="checkbox"/>
289233	WELL	PR	10/30/2009	GW	045-13686	LATHAM 32-21D	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>8</u>	Production Pits: <u>1</u>
Condensate Tanks: <u>4</u>	Water Tanks: <u>1</u>	Separators: <u>2</u>	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
CONTAINERS	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			08/26/2016
BATTERY	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: 970-285-2200

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Equipment:

Type: Bird Protectors	# 8	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date: _____		
Type: Horizontal Heated Separator	# 8	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action	Date: _____		
Type: Ancillary equipment	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment	Chemical containers at wells		
Corrective Action	Date: _____		
Type: Plunger Lift	# 8	Satisfactory/Action Required:	SATISFACTORY

Comment	
Corrective Action	Date:

Tanks and Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	100 BBLS	PBV STEEL	,

S/AR	SATISFACTORY	Comment:	
------	--------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Tanks and Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
METHANOL	1	<50 BBLS	STEEL AST	,

S/AR	SATISFACTORY	Comment:	
------	--------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) 500 bbl _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Tanks and Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	4	300 BBLS	HEATED STEEL AST	,

S/AR	SATISFACTORY	Comment:	
------	--------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Inspector Name: LONGWORTH, MIKE

Other (Capacity) _____				
Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:	
Yes/No	NO
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

<u>Predrill</u>			
Location ID:	335842		
Lease Road Adeq.:		Pads:	Soil Stockpile:
S/AR:			
Corrective Action:		Date:	CDP Num.:

Form 2A COAs:			
Group	User	Comment	Date
OGLA	kubeczko	<p>GENERAL SITE AND ROAN RIM COAs:</p> <p>Operator must comply with all provisions of the June 12, 2008 Notice to Operators (NTO) Drilling Wells Within ¾ Mile of the Rim of the Roan Plateau in Garfield County – Pit Design, Construction, and Monitoring Requirements.</p> <p>After installation of the uppermost liner and prior to operating the pit, the synthetic liner(s) shall be tested by filling the pit with at least 4 feet of fresh water, measured from the base of the pit (not to exceed the 2-foot freeboard requirement). The operator shall monitor the pit for leaks for a period of 72 hours prior to draining the pit and commencing operations. Operator shall notify the COGCC Oil and Gas Location Assessment (OGLA) Specialist for Western Colorado (Dave Kubeczko; email dave.kubeczko@state.co.us) 48 hours prior to start of the hydrotest. Hydrotest monitoring results must be maintained by the operator for the life of the pit and provided to COGCC prior to using the pit.</p> <p>Operator must ensure 110 percent secondary containment for any volume of fluids contained at the water handling facility site during natural gas development activities and operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures (i.e., best management practices (BMPs) associated with stormwater management) sufficiently protective of nearby surface water. Any berm constructed at the well pad location will be stabilized, inspected at regular intervals (at least every 14 days), and maintained in good condition.</p> <p>Operator must implement best management practices to contain any unintentional release of fluids, including any fluids conveyed via buried or temporary surface pipelines.</p>	03/22/2011

Notify COGCC Oil and Gas Location Assessment (OGLA) Specialist for Western Colorado (Dave Kubeczko; email dave.kubeczko@state.co.us) and the COGCC Field Inspection Supervisor for Northwest Colorado (Shaun Kellerby; email shaun.kellerby@state.co.us) 48 hours prior to start of construction or use of existing pit.

No portion of any pit that will be used to hold liquids shall be constructed on fill material, unless the pit and fill slope are designed and certified by a professional engineer, subject to review and approval by the director prior to construction of the pit. The construction and lining of the pit shall be supervised by a professional engineer or their agent. The entire base of the pit must be in cut.

The completion/flowback fluids multi-well pit must be double-lined. The pit will also require a leak detection system (Rule 904.e).

Operator must submit a professional engineer (PE) approved/stamped as-built drawing (plan view and cross-sections) of the completion/flowback pit within 14 calendar days of construction.

The nearby hillside and fill-material bermed portions of the pit must be monitored for any day-lighting of fluids throughout pit operations.

The completion/flowback fluids multi-well pit must be fenced and netted. The operator must maintain the fencing and netting until the pit is closed in accordance with Rule 905. Closure of Pits, and Buried or Partially Buried Produced Water Vessels.

Flowback and stimulation fluids must be sent to tanks to allow the sand to settle out before the fluids can be placed into any pipeline or pit. The flowback and stimulation fluid tanks must be placed on the pad in an area with additional downgradient perimeter berming. The area where flowback fluids will be stored/reused must be constructed to be sufficiently impervious to contain any spilled or released material (per Rule 604.a.(4)).

Submit additional disposal facilities (wells, pits, etc.) for pit contents to COGCC via a Form 4 Sundry prior to disposal.

Surface water samples from Little Creek and the north tributary to Little Creek Operator shall be collected prior to pit use and every 12 months to evaluate potential impacts from pit operations. At a minimum, the surface water samples will be analyzed for the following parameters: major cations/anions (chloride, fluoride, sulfate, sodium); total dissolved solids (TDS); and BTEX/DRO.

At the time of pit closure, operator must submit disposal information via a Form 4 Sundry Notice to the COGCC Location Specialist for Western Colorado (Dave Kubeczko; email dave.kubeczko@state.co.us). The disposal method will need to be approved prior to operator starting pit closure. In addition, operator will collect a pit water sample and, at a minimum, analyze for the following parameters: pH; alkalinity; specific conductance; major cations/anions (chloride, fluoride, sulfate, sodium); total dissolved solids (TDS); BTEX/DRO; TPH; PAH's (including benzo[a]pyrene); and metals (arsenic, barium, calcium, chromium, iron, magnesium, selenium). At the time of closure/disposal of pit water, COGCC may require additional analytes, as appropriate.

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Inspector Name: LONGWORTH, MIKE

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 289226 Type: WELL API Number: 045-13693 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 289227 Type: WELL API Number: 045-13692 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 289228 Type: WELL API Number: 045-13691 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 289229 Type: WELL API Number: 045-13690 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 289230 Type: WELL API Number: 045-13689 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 289231 Type: WELL API Number: 045-13688 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 289232 Type: WELL API Number: 045-13687 Status: PR Insp. Status: PR

Producing WellComment: **Producing well**

Facility ID: 289233 Type: WELL API Number: 045-13686 Status: PR Insp. Status: PR

Producing WellComment: **Producing well****Environmental****Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment: **Land farm on west edge of location.**

1003a. Waste and Debris removed?

CM

CA CA Date

Unused or unneeded equipment onsite?

CM

CA CA Date

Pit, cellars, rat holes and other bores closed?

CM

CA CA Date

Guy line anchors marked?

CM

CA CA Date

Inspector Name: LONGWORTH, MIKE

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Culverts	Pass			
		Ditches	Pass			
Berms	Pass					
				Material Handling And Spill Prevention	Pass	

Inspector Name: LONGWORTH, MIKE

S/A/V: SATISFACTORY Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Pit Type: _____ Lined: NO Pit ID: _____ Lat: 39.575690 Long: -108.198040

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Open pit on location not found in database. See 08/13/2014 inspection doc # 671000049

Fencing:

Fencing Type: _____ Fencing Condition: Inadequate

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/A/V): ACTION Comment: _____

Corrective Action: Contact COGCC EPS and Reclamation staff regarding drilling pit closure per rules 905.a and 1003.d.

Date: 08/26/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703038	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3931221