

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
08/16/2016  
Document Number:  
679901785  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 300722      | 311261 | Welsh, Brian    | <input type="checkbox"/> |             |

**Operator Information:**

OGCC Operator Number: 75027  
 Name of Operator: ROSEWOOD RESOURCES INC  
 Address: 2101 CEDAR SPRINGS RD STE 1500  
 City: DALLAS State: TX Zip: 75201

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name     | Phone             | Email                 | Comment                  |
|------------------|-------------------|-----------------------|--------------------------|
| Krehmeyer, James | 970-630-3880 cell | jkrehmeyer@rosewd.com | Keller Cattle Field Insp |

**Compliance Summary:**

QtrQtr: NWSW Sec: 15 Twp: 2S Range: 46w

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 09/16/2015 | 679900395 | PR         | PR          | SATISFACTORY                  |          |                | No              |
| 04/02/2014 | 668602439 | PR         | PR          | SATISFACTORY                  | Pass     |                | No              |
| 09/08/2011 | 200321083 | PR         | PR          | <b>ACTION REQUIRED</b>        |          |                | Yes             |

**Inspector Comment:**

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|-------------------------------------|
| 300722      | WELL | PR     | 08/01/2012  | GW         | 125-11655 | Johnson Prescott 13-15 2S46W | PR          | <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                                 |                         |                      |                          |
|---------------------------------|-------------------------|----------------------|--------------------------|
| Special Purpose Pits: _____     | Drilling Pits: <u>1</u> | Wells: <u>1</u>      | Production Pits: _____   |
| Condensate Tanks: _____         | Water Tanks: _____      | Separators: <u>1</u> | Electric Motors: _____   |
| Gas or Diesel Mortors: <u>1</u> | Cavity Pumps: _____     | LACT Unit: _____     | Pump Jacks: <u>1</u>     |
| Electric Generators: _____      | Gas Pipeline: <u>1</u>  | Oil Pipeline: _____  | Water Pipeline: <u>1</u> |
| Gas Compressors: _____          | VOC Combustor: _____    | Oil Tanks: _____     | Dehydrator Units: _____  |
| Multi-Well Pits: _____          | Pigging Station: _____  | Flare: _____         | Fuel Tanks: _____        |

**Location**

| <b>Lease Road:</b> |                              |                           |                   |      |
|--------------------|------------------------------|---------------------------|-------------------|------|
| Type               | Satisfactory/Action Required | comment                   | Corrective Action | Date |
| Access             | SATISFACTORY                 | Two track through pasture |                   |      |

| <b>Signs/Marker:</b> |                              |                        |                   |         |
|----------------------|------------------------------|------------------------|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment                | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 | Lease sign by wellhead |                   |         |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |  |                   |         |
|------------------|------------------------------|--|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment  | Corrective Action | CA Date |
| WELLHEAD         | SATISFACTORY                 | Metal panels around wellhead, VGS and meter shed |                   |         |

| <b>Venting:</b> |    |
|-----------------|----|
| Yes/No          | NO |
| Comment         |    |

| <b>Flaring:</b>    |                              |                      |  |
|--------------------|------------------------------|----------------------|--|
| Type               | Satisfactory/Action Required |                      |  |
| Comment:           |                              |                      |  |
| Corrective Action: |                              | Correct Action Date: |  |

**Predrill**

Location ID: 300722

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: SATISFACTORY **Comment:** No COAs

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ **Comment:** \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 300722 Type: WELL API Number: 125-11655 Status: PR Insp. Status: PR

**Producing Well**

**Comment:** Producing. Casing production

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

|   |                   |             |      |
|---|-------------------|-------------|------|
| <b>Water Well:</b>  |                   | Lat         | Long |
| DWR Receipt Num: _____  | Owner Name: _____ | GPS : _____ |      |
| <b>Field Parameters:</b>  |                   |             |      |
|   |                   |             |      |
| Sample Location: _____  |                   |             |      |
|   |                   |             |      |
| Emission Control Burner (ECB): _____                            |                   |             |      |
| Comment: _____  |                   |             |      |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ |                   |             |      |

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Welsh, Brian

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

S/A/V: SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 679901785    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3931622">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3931622</a> |