

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date: 08/18/2016
Document Number: 684902016
Overall Inspection: **ACTION REQUIRED**

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|-----------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>317524</u> | <u>317524</u> | <u>Pesicka, Conor</u> | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 10575
Name of Operator: 8 NORTH LLC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------|---|
| | | COGCCInspections@extracti onog.com | All Inspections inc 8 North, 7 North, XPR |

Compliance Summary:

QtrQtr: NENW Sec: 33 Twp: 12N Range: 61W

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 239069 | WELL | PR | 03/01/2007 | OW | 123-05952 | PETERS #3 | PR | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|-----------------------------|---------------------------------------|-------------------|
| WELLHEAD | ACTION REQUIRED | Sign is for prior operator. | Install sign to comply with rule 210. | 10/18/2016 |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____
Comment: _____
Corrective Action: _____

| | | | | |
|----------------|------|--------|-------------------|---------|
| Spills: | | | | |
| Type | Area | Volume | Corrective action | CA Date |

Multiple Spills and Releases?

| | | | | |
|------------------|------------------------------|--------------|-------------------|---------|
| Fencing/: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| PUMP JACK | SATISFACTORY | cattle panel | | |

| | | | | |
|-------------------|---|---|--|-----------------|
| Equipment: | | | | |
| Type: Prime Mover | # 1 | Satisfactory/Action Required: SATISFACTORY | | |
| Comment | electric | | | |
| Corrective Action | | | | Date: |
| Type: Pump Jack | # 1 | Satisfactory/Action Required: ACTION REQUIRED | | |
| Comment | Stained soil around wellhead | | | |
| Corrective Action | Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. | | | Date: 9/19/2016 |

| | | | | |
|-----------------------------------|--------------------------------|----------------|---------------------|------------------|
| Tanks and Berms: | | | | |
| <input type="checkbox"/> New Tank | | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS |
| | | | CENTRALIZED BATTERY | , |
| S/AR | Comment: Refer to locid#317545 | | | |
| Corrective Action: | | | | Corrective Date: |

| | | | | |
|------------------|-------|--|--|--|
| Paint | | | | |
| Condition | | | | |
| Other (Content) | _____ | | | |
| Other (Capacity) | _____ | | | |
| Other (Type) | _____ | | | |

| | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| | |
|-----------------|----|
| Venting: | |
| Yes/No | NO |
| Comment | |

| | | | |
|--------------------|------------------------------|--|----------------------|
| Flaring: | | | |
| Type | Satisfactory/Action Required | | |
| Comment: | | | |
| Corrective Action: | | | Correct Action Date: |

Predrill

Location ID: 317524

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 239069 Type: WELL API Number: 123-05952 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead plumbed to surface

CA: _____

CA Date: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): N _____
 Comment: Refer to locid#317545
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION
Cropland
 Top soil replaced _____ Recontoured _____ Perennial forage re-established _____
Non-Cropland

Inspector Name: Pesicka, Conor

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 684902022 | Sign is for prior operator | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3932470 |
| 684902024 | Stained soil at welhead | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3932471 |