



Photo#1: Musk Thistle (Noxious Weed) patches are establishing on Location.

August 16, 2016

Inspection Photos: GRMR AL Built API#081-07775



Photo#2: Large areas of Location vegetation are predominately weeds.

Inspection Photos: GRMR AL Built API#081-07775

August 16, 2016



Photo#3: Close up of dominate Weedy Species.

Inspection Photos: GRMR AL Built API#081-07775

August 16, 2016



Photo#4: Close up of Ground Conditions; grazed grass plants and matured weeds.

Inspection Photos: GRMR AL Built API#081-07775

August 16, 2016



Photo#5: Reference area Vegetation.

Inspection Photos: GRMR AL Built API#081-07775

August 16, 2016