

## Final Reclamation Inspection- Bond Release



**Photo 1.** Photo taken of HRM Resources PR well sign for API#123-12206. This is a well release for API#'s 123-29110 and 123-29111 on an active location not leased by Texas American Resources.

## Final Reclamation Inspection- Bond Release



**Photo 2.** Photo taken of HRM Resources PR well sign for API#123-12206. This is a well release on an active location not leased by Texas American Resources.