

Reclamation Inspection

08/19/2016

Operator: Diversified Operating

Location ID: 408318

Weld County, CO

NENE Section 20 T8N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from the south end of the location, facing northwest. Photo shows large, unvegetated areas of the location. Evidence of erosion occurring on location.



Figure 2: Photo taken from the south end of the location, facing north. Photo shows large, unvegetated areas of the location. Evidence of erosion occurring on location



Figure 3: Photo taken from the south end of the location, facing east. Photo shows large, unvegetated areas of the location. Evidence of erosion occurring on location



Figure 4: Photo taken from the location. Photo shows large bare areas on location where erosion is occurring. 6' measuring stick for reference.



Figure 5: Photo taken from the location. Photo shows large bare areas on location where erosion is occurring. 6' measuring stick for reference. Arrow shows remnants of a sediment control blanket no longer in proper functioning condition, and is now debris.



Figure 6: Photo taken from the location. Photo shows large bare areas on location where erosion is occurring. 6' measuring stick for reference.



Figure 7: Photo taken from the location. Photo shows large bare areas on location where erosion is occurring. Photo also shows remnants of a sediment control blanket no longer in proper functioning condition, and is now debris.