

Reclamation Inspection

08/19/2016

Operator: Whiting

Location ID: 427525

Weld County, CO

Lot 4 Section 5 T9N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo taken from the west end of the location, facing southeast. Photo shows interim reclamation in process.



Figure 2: Photo taken from the west end of the location, facing east. Photo shows interim reclamation in process.



Figure 3: Photo taken from the west end of the location, facing northeast. Photo shows interim reclamation in process.



Figure 4: Photo taken from the west end of the location, facing northeast. Photo shows interim reclamation in process.



Figure 5: Photo taken from the north end of the location, facing southeast. Photo shows interim reclamation in process.



Figure 6: Photo taken from the north end of the location, facing south. Photo shows interim reclamation in process.



08.19.2016 14:53

Figure 7: Photo taken from the county road west of the location, facing east. Photo shows interim reclamation in process.